



UL

• Directions for use • Manual de instrucciones



MAX 8m	LED		IP 65	220-240V 50-60Hz	max 11kg	AstroDIM	DALI	StepDIM
---------------	------------	--	--------------	-----------------------------	-----------------	-----------------	-------------	----------------

UL	FLUX, lm	UL	FLUX, lm
UL 3500	3500	UL 9000	9000
UL 5000	5000	UL 11500	11500
UL 7500	7500	UL 14000	14000








↓ 5.1

M8x45 ↓ 5.2



L N ⊕ SD DA
L N ⊕ DA DA



Attention! The lighting unit may only be assembled by a skilled firm or by person with electrotechnical qualification. The light source of this luminaire is not replaceable, when the light source reaches its end of life the whole luminaire should be replaced.



The warranty period of this product is 24 months from the purchase date. The warranty doesn't cover damage caused by improper handling.

UL

• Directions for use • Manual de instrucciones



MAX 8m	LED		IP 65	220-240V 50-60Hz	max 11kg	AstroDIM	DALI	StepDIM
---------------	------------	--	--------------	-----------------------------------	-----------------	-----------------	-------------	----------------

UL	FLUX, lm	UL	FLUX, lm
UL 3500	3500	UL 9000	9000
UL 5000	5000	UL 11500	11500
UL 7500	7500	UL 14000	14000








$\phi 42$ ↓ 5.1

M8x45 ↓ 5.2



LN @SD DA
LN @DA DA



Upozornění! Montáž svítidla smí provádět pouze odborná elektromontážní firma nebo osoba s elektrotechnickou kvalifikací.
 Attention! The lighting unit may only be assembled by a skilled firm or by person with electrotechnical qualification.
 The light source of this luminaire is not replaceable, when the light source reaches its end of life the whole luminaire should be replaced.
 The warranty period of this product is 24 months from the purchase date. The warranty doesn't cover damage caused by improper handling.
 Attention! les luminaires doivent être posés par des sociétés spécialisées ou par des personnes compétentes ayant le diplôme d'électrotechnicien.